



10th May 2018, University of Valladolid

Electrical machines fault detection

Lucia FROSINI

Department of Electrical, Computer and Biomedical Engineering Faculty of Engineering University of Pavia Pavia, Italy E-mail: lucia@unipv.it



L. Frosini







L. Frosini

What is diagnostics?

Diagnostics is a procedure of "translation" of the information arising from the measurement of parameters related to a machine (or a system) in information regarding the effective or incipient faults of the machine itself.

In other words, diagnostics is the complex of the activities of analysis and synthesis which - by using the acquisition of certain physical quantities, characteristic of the monitored machine - allows to draw significant information on the <u>condition of the machine</u> and on its <u>trend during the time</u>, for the evaluation of its reliability in short and long term.

L. Frosini

1

What is diagnostics?

University of Pavia, Faculty of Engineering

The targets of the diagnostics are:



The general problem of diagnostics is to detect if a specific fault is present (or not) on the basis of the available information, <u>preferably without an intrusive inspection</u> of the machine.

Hypothesis test

This problem can be described with a statistical approach as a problem of <u>hypothesis test</u>:

- null hypothesis H₀: the fault is present;
- alternative hypothesis H₁: the fault is not present.

The hypothesis test is subject to two types of error:

- <u>type I error</u> happens when the null hypothesis H₀ is true and you reject it: when, on the basis of the available information, you decide that the fault is not present, but actually it is. Therefore, the machine is not stopped and repaired before the effective manifestation of the failure, with possible catastrophic consequences.
- <u>type II error</u> happens when the null hypothesis is false and you fail to reject it: when, on the basis of the available information, you decide that the fault is present, but actually it is not. Therefore, the machine is stopped and repaired in vain, with <u>useless economic costs</u>

L. Frosini

Steps of diagnostics

Diagnostics is not an exact science!

A diagnostic program develops according to the following steps:

- a) data acquisition,
- b) data processing,
- c) decision-making.

The methods employed for the acquisition and elaboration of the data and for the choice of the threshold which separates the <u>faulty condition</u> from the <u>healthy condition</u> of a component can heavily influence the chance to make an error during the phase of the decision making.

If the decision is made by an individual, we can talk about "fault detection", if the decision is given by an automatic algorithm, we can talk about "diagnosis".

L. Frosini

Subject of diagnostics

If the subject of diagnostics is a rotating electrical machine, it is important to note that its operation cannot be considered separately from:

- the operation of the mechanical machine connected along its axis line (pump, fan or another load for an electrical motor; turbine or another prime motor for an electrical generator);
- the type of the mechanical coupling (joint, gears, belts, etc.);
- the possible control system (inverter, etc.).

All these mechanical and electronic systems can:

- induce faults in the electrical machine,
- arouse changes in the parameters of the electrical machine, even in absence of fault;
- experience faults induced by the electrical machine.

L. Frosini

5

Main parts of cage induction motor

In this seminar we consider, as subject of diagnostics, the three-phase induction motor and, in particular, the type with cage rotor, since it is more widespread with respect to the wound rotor.



7

8

Main parts of cage induction motor



Three-phase induction motor of low power (2 kW), fed at low voltage (400 V), with aluminium die-cast rotor

9

L. Frosini

Where the faults can happen in the motors?

In the literature, only two extensive (and quite old) surveys on the faults in electrical motors are present, one dated 1985 and the other one 1995: since the latter is limited to the petrochemical industry, normally we refer to the results reported in the first survey, developed by the Electric Power Research Institute (EPRI):



Note that the frequency of occurrence of these faults depends heavily on the specific application of the machine.

L. Frosini

Main parts of cage induction motor

For higher power and voltage, the manufacture characteristics are different: different insulation of the stator windings (form-wound) and rotor bars inserted in the slots and welded to the short-circuit rings (not die-cast).

Wound stator and cage fabricated rotor of a threephase induction motor of 1.8 MW, at 6 kV





10

L. Frosini

Possible indicators of fault

Diagnostics and condition monitoring require the measurement and the analysis of some signals that contain characteristic information (symptoms) about the process of wear, malfunctions or incipient faults.

The following factors should be considered in the selection of the more appropriate diagnostic techniques:

- 1) The sensor should be (possibly) non-invasive;
- 2) The sensor and the measurement system must be reliable;
- 3) The diagnosis must be reliable;
- 4) The severity of the problem should be quantified;
- 5) Ideally, you should have an evaluation of the remaining life time;
- 6) Ideally, the information obtained from the sensor should provide an indication of the "root causes" which produced the fault.

In many cases, it is possible to meet the criteria from 1) to 4), whereas those from 5) to 6) are extremely difficult to achieve.

Possible indicators of fault

In an electrical machine, different aspects (electrical, magnetic, mechanical, fluid dynamics, thermal) interact in a complex manner, as shown in the figure:



L. Frosini

Possible indicators of fault

Further possible indicators of fault are:

- the measurement of the efficiency, which requires the measurement of both input and output power, therefore both electrical and mechanical parameters in case of rotating electrical machine.
- the visual analysis of different parts of the machine, during the revisions involving their dismantling: this analysis is based on objective parameters, but also on the experience of the technical staff.

If present, the **control and supervision** system, governing the overall installation, and the **power electronics**, specializing in translating the commands in energy signals supplied to the machine, can be considered as important parts in the scheme of diagnostics and condition monitoring.

L. Frosini

Possible indicators of fault

Various parameters belonging to these different fields can be suitable as potential fault indicators in electrical machines:



L. Frosini

MCSA to detect induction motor faults

In the last years, the traditional diagnostic techniques, based on the vibration measurement, have been progressively abandoned in favour of an approach focused on the **analysis of electromagnetic signals**, in particular the **stator current** (MCSA) and the external **stray flux** around the motor.

The aim is to employ less sensors, possibly already present in the electrical drive for the control of the machine.

MCSA to detect induction motor faults

The possible faults which can be detected by means of MCSA are:

1)	Broken rotor bars	 <u>slowly</u> progressive faults <u>primary</u> effect on airgap flux and therefore on stator current 	
2)	Rotor eccentricities	well known and established methodology, from many years	
3)	Stator short circuits \rightarrow	 <u>quickly</u> progressive fault <u>primary</u> effect on airgap flux and therefore on stator current well known theory, but <u>still not applied</u> in real cases 	
4)	Bearing faults \longrightarrow	 <u>slowly</u> progressive fault <u>secondary</u> (and often <u>weak</u>) effect on airgap flux and therefore on stator current well known theory (but not valid for any type of bearing fault), <u>still not applied</u> in real cases 	17

Broken rotor bars



L. Frosini

Broken rotor bars

Broken rotor bars can be a serious problem, especially for large induction motors with heavy duty cycles.

Broken rotor bars do not directly cause a breakdown of the motor, but they can give rise to severe secondary effects: the fault mechanism can result in broken parts of the bar hitting the stator winding. This can cause a serious mechanical damage to the insulation of the stator winding, with a consequential winding failure, resulting in a costly repair and lost production.

Broken rotor bars or end rings can be caused by:

- Direct-on-line starting duty cycles for which the rotor cage winding was not designed to withstand;
- Pulsating mechanical loads;
- Imperfections in the manufacturing process of the rotor cage.

W.T. Thomson, R.J. Gilmore, "Motor current signature analysis to detect faults in induction motor drives -Fundamentals, data interpretation, and industrial case histories", in Proc. Turbomachinery Symposium, pp. 145-156, Houston (Texas), USA, 2003.

L. Frosini

19

I. Frosini

Types of rotor

In general, induction machines can be equipped with the following types of rotor:

wound rotor, with three-phase winding consisting of copper wires and three short-circuit rings.

4 squirrel cage rotor, with a multi-phase winding consisting of bars and two frontal short-circuit rings at opposite sides. The cage rotor can be die-cast or fabricated (with the bars inserted in the slots and welded to the frontal rings). In the first case, the bars are almost always made of aluminium (but they can be made of copper or copper alloys), whereas in the second case they are almost always made of **copper**.





Die-cast cage rotor

The die-cast cage rotor is normally used in low and medium power induction motors (about <250 kW).

The whole cage is formed in a single piece by pouring molten metal (usually aluminium) into a mould.

die-cast aluminium rotor

The bars are generally skewed with respect to the stator slots.



die-cast copper rotor



21

23

Die-cast cage rotor

In recent years, the manufacturing technique of die-cast **copper** cage rotors is spreading (until tens of kW), in order to improve the motor efficiency.

The manufacturing process of this type of rotor, compared to the die-cast aluminium cage, presents higher energetic and economic costs and it is technically more complex.

(copper melts at 1083 ° C, aluminium at 658 ° C)





22

L. Frosini

Fabricated cage rotor

For high power induction motors (about >250 kW), which can be supplied at low (<700 V) or high voltage (>700 V), the rotor consists of **copper** bars that are inserted into the slots and welded to the frontal short circuit rings.





2800 kW, 6600 V, 2 poles

900 kW, 6000 V, 8 poles

L. Frosini

I. Frosini

Fabricated cage rotor

Other examples of fabricated cage rotors:







Fabricated cage rotor for a 3 MW motor, 6 kV, 2 poles

300 kW, 3300 V

Broken bars in fabricated cage rotor

For these rotors, the most likely failure is due to the breakage of a bar or a fracture near the point of contact between bar and ring.





900 kW, 6 kV, 8 poles

3100 kW, 11 kV, 2 poles

25

L. Frosini

Phenomenon of rotor bar breaking

This failure is generally caused by thermal stresses and frequent startups.

This deterioration is slowly progressive, therefore a diagnostic tool can be effective in preventing it!

The start-up is a critical phase for the cage: the high temperature produced by the high currents (until 8-10 times the rated one) causes expansion of the bars, favouring the possible occurrence of fractures or detachments at the point of contact between bar and ring (due to mechanical fatigue, welding failure, etc.).

The consequent increase of impedance in the bar subject to the failure results in a redistribution of the currents in the healthy bars, arousing an imbalance of the magnetic flux produced by the rotor, which in turn causes an imbalance in the stator currents. L. Frosini

Broken bars in fabricated cage rotor

Other examples of rotors with broken bars:





Ex.: 2600 kW, 4160 V, 2 poles

If the failure is detected before the complete breakdown of the motor: Motor repair cost: \$ 60,000 (repair) + \$ 30,000 (planned plant shutdown). Otherwise: motor replacement cost: \$ 170,000 (new motor) + \$ 200,000 (unscheduled plant shutdown).

http://pdma.com/pdfs/cs/Case_Studies_in_Online_and_Offline_Motor_Analysis.pdf

L. Frosini





The imbalance of the stator currents produces a backward rotating field.

As a consequence, there will be an increase of the currents in both windings (remarkable on the rotor, lower on the stator) and an increase of their temperatures.

The redistribution of the currents in the healthy bars, associated with the temperature increase, results in <u>increased mechanical and thermal stresses on</u> the adjacent bars to the broken one.

This causes the propagation of the failure.

This is usually a <u>chain phenomenon</u>, as the first broken bar causes more stress on the adjacent bars, which therefore deteriorates more quickly.





These phenomena also produce an oscillating torque at twice the slipping frequency (2sf) which gives rise to a ripple in the rotational speed and consequently to an amplitude reduction of the stator current component I_{left} at frequency (1-2s)f.

As a further effect, the rotational speed oscillating phenomenon produces another stator current component I_{right} at frequency (1+2s)f.

L. Frosini

Asymmetric rotor



With a healthy and symmetric rotor, the electromotive force induced in the rotor circuit have frequency sf (arrow from f to sf).

The presence of an <u>asymmetry in the rotor electric circuit</u> determines a backward rotor field $(-sf_1)$ with a rotor current component at frequency -sf.

The stator "sees" a backward rotating rotor field at frequency:

 $-sf_1 + f_r = -sf_1 + (1-s)f_1 = f_1 - 2sf_1 = (1-2s)f_1$

This backward rotating rotor field induces an electromotive force in the stator and hence a stator current component I_{left} at frequency (1-2s)f : arrow from -sf to (1-2s)f.

The stator current component $\rm I_{left}$, induced by the rotor asymmetry, interacts with the rotor current component at frequency -sf: arrow from (1-2s) f to -sf.

L. Frosini

Motor current signature analysis

So, the left current component, at frequency (1-2s)f, is directly related to the rotor failure, while the right current component, at frequency (1+2s)f, is caused by the speed ripple effect and its amplitude varies with the value of the combined rotor-load inertia. The effect of the speed ripple also affects the amplitude of the left current component.

In general, the detection of broken bars based on the current sidebands analysis at frequencies $(1\pm 2s)f$ is successful.

In the following, the experimental results related to a motor with aluminium die-cast rotor, 1.5 kW, 220 V, 50 Hz, 4 poles, nominal slip 6%, 28 rotor bars are presented. Three rotors were tested: i) healthy, ii) with one broken bar, iii) with two broken bars.

A. Bellini C. Concari, G. Franceschini, C. Tassoni, A. Toscani, "Vibrations, currents and stray flux signals to asses induction motors rotor conditions, IEEE Industrial Electronics", in *Proc. IECON 2006*.

Motor current signature analysis

The amplitude of the sidebands at frequencies $(1\pm2s)f$ in the stator current spectrum depends on:

- number of broken bars (increases with the number);
- load percentage (increases with the load).



Drilled hole in the end ring



L. Frosini

External stray flux

a) at no-load b) at half load

c) at full load

It is expected that stray flux includes the same information obtained by the stator current.

In fact, the sideband components at frequencies $f\pm 2sf$ are still present. As before, their amplitudes depend on the machine load.

Notice that the right side component amplitude increases with slip more than the left one, because the e.m.f. (i.e. the flux derivative) is measured instead of the flux.

The signal is weaker than the stator current.

a) at no-load 2 broken bars b) at half load c) at full load



L. Frosini

External stray flux

In the same experimental tests, the e.m.f. induced by the **external stray flux** has been measured by means of a sensor consisting of 300 turns wound on a C-shaped magnetic core of rectangular cross-section (25x10 mm²), positioned on the motor frame.



The external stray flux is the magnetic flux that radiates outside of the motor frame. Its magnitude is related to the place where the sensor is located around the machine body.

It is induced by both the stator and rotor currents, even if stator currents prevail, due to the magnetic shield effect provided by the stator against the rotor currents. Specifically, one or two stator phase currents dominate, due to the fixed position of the sensor and the distribution of the three-phase stator winding.

L. Frosini

External stray flux

In summary, stator current and stray flux signals can be used with the same effectiveness in order to detect and quantify rotor faults.

The optimal choice depends on the specific application and on the easiness of installing flux or current sensors in the specific industrial environment.





36

Issues in the detection of broken bars

In practice, <u>motors with a limited number of broken bars are usually still able</u> to perform their operation without evident anomalies, as increased mechanical vibration or lengthening of the run-up time.

However, the motor does not remain in this condition for a long time, since the aging process is greatly accelerated by the chain reaction above described.

One issue in the detection of broken bars by MCSA is that the amplitude of the spectral components of the stator current due to a single broken bar is often in the order of magnitude of that induced by the intrinsic constructive asymmetries of a healthy machine, and therefore it is difficult to distinguish between the two cases.

Issue due to oscillating torques

Moreover, an oscillating torque produced by the load, without the presence of rotor asymmetries or rotor failures, produces sidebands in the stator current spectrum which, in some cases, may appear close to the frequencies due to the broken rotor bars.



Therefore, for a more in-depth (but also more expensive) diagnostic analysis, it may be useful to consider together different electromagnetic and mechanical parameters, measured by current probes, flux sensors, accelerometers and temperature transducers.

L. Frosini

Radial vibration spectrum

Here we can see that even the amplitude of the sidebands at frequencies $f_r \pm 2sf$ in the spectrum of the radial vibration depends on:

- number of broken bars (increases with the number);
- load percentage (increases with the load).

a) at no-load b) at half load c) at full load

Red: healthy Blue: faulty



L. Frosini

37

39

I. Frosini

Issue due to the rotor bar skewing

Practically, almost cage rotors are skewed:



Pros:

- Reduction of torque ripple (reduction of the parasitic torques and the consequent risk of cogging during the startup)
- Noise reduction during the normal operation

Cons:

 Increase of the inter-bar currents

40

Rotor bar skewing and its effects

The inter-bar current is the current flowing between adjacent bars of a cage rotor, through the magnetic iron core, which produces a non-uniform distribution of the current along the axial length of the machine.

Since there is **no insulation between bar and core**, only the <u>bar-core</u> <u>contact resistance</u> limits the current flowing in the core.

Some researches have highlighted that this contact resistance is about 70 times greater than the iron resistance.

In the classical theory of induction machines, the inter-bar currents are generally neglected.

The usual assumption is that aluminium (or copper) bar resistance is much lower than iron core resistance and bar-core contact resistance, so the current completely flows along the bars.

L. Frosini

Rotor bar skewing and its effects

On the contrary, several experimental studies have proven that current flows also between adjacent bars through the iron core.

This phenomenon is accentuated in skewed cage rotors because the natural path for the rotor current is along the axial length of the bar, but it is forced along the skewed bar direction.

In fact, in an induction motor, the **magnetic flux is radial**, the induced electromotive force on the rotor is axial and therefore also the **current should be axial**.



41

L. Frosini

Rotor bar skewing and its effects

Other researches have shown that:

- ✓ Inter-bar currents become remarkable when a bar is broken;
- ✓ Resistivity between bars is lower in case of copper die-cast rotors than aluminum die-cast rotors.

If inter-bar currents are relatively high even in a healthy motor, then, in case of broken bar, the current flowing between the adjacent bars to the broken one (near to the short circuit ring, where the break is present) will become higher, causing a chain reaction that could more easily break the adjacent bars.

From a diagnostic point of view, these **high inter-bar currents can reduce the imbalance caused by a broken bar:** this effect can make harder the early detection of the broken bar, when the sidebands currents around the fundamental are monitored.

L. Frosini

Effect of the inter-bar currents on the diagnostics

The diagnostic procedure based only on the stator current analysis for the detection of a broken rotor bar may fail if remarkable inter-bar currents are present, since they reduce the degree of asymmetry of the rotor and, consequently, the amplitude of the considered spectral components.

On the other hand, the presence of inter-bar currents has a further effect on the rotor vibrations: the **interaction of the radial magnetic flux with the inter-bar currents**, which flow tangentially along the rotor circumference, produces a force (and hence a vibration) in the axial direction.

Therefore, the analysis of the previously considered parameters (stator current, stray flux, radial vibrations) together with the **axial vibration** can increase the effectiveness of the proposed diagnostic procedure.

Effect of the inter-bar currents on the diagnostics

C. Concari, G. Franceschini, C. Tassoni, "Differential diagnosis based on multivariable monitoring to assess induction machine rotor conditions", *IEEE Trans. on Industrial Electronics*, Vol. 55, No. 12, 2008.



Fig. 8. Interbar currents in case of (a) bar breakage and (b) generation of an axial force.

Fig. 19. Axial vibration signal spectra in the range close to f_r (blue two broken bars, red healthy) (a) no load, (b) half load, and (c) full load.

L. Frosini





(c)

L. Frosini

Effect of the inter-bar currents on the diagnostics

The graphs in the previous slide refer to a small induction motor (1.5 kW, 4 poles) with die-cast aluminium cage: in this case, the currents between bars in presence of one or two broken bars are negligible and the rotor diagnosis by means of the stator current analysis is still effective.

Another research has considered a higher power motor (55 kW, 2 poles, with copper cage and skewed bars) and has verified that a broken bar modifies the axial vibrations at particular frequencies.

G.H. Muller, C.F. Landy, "A novel method to detect broken rotor bars in squirrel cage induction motors when interbar currents are present", *IEEE Trans. on Energy Conversion*, Vol. 18, Issue 1, 2003.

L. Frosini

45

Airgap eccentricity

Airgap eccentricity causes a force on the rotor, called Unbalanced Magnetic Pull (UMP), that tries to pull the rotor even further from the stator bore centre, in the direction of the minimum airgap. If the levels of eccentricity are not kept within specified limits (typically <10%), then eccentricity can cause excessive stress on the motor and <u>can increase bearing wear</u>.

Moreover, the radial magnetic force waves produced by eccentricity act on the stator and rotor, thus exposing the stator and rotor windings to potentially <u>harmful vibrations</u>. Besides, acoustic noise levels can substantially increase.

High UMP due to severe airgap eccentricity can ultimately lead to a <u>rotor to</u> <u>stator rub</u>, with consequential damage to the stator core, stator windings and rotor cage. This can cause <u>insulation failure of the stator winding</u> or <u>breaking</u> <u>of the rotor cage</u> bar or end rings and, hence, a costly repair, in case of high power induction motor.



Airgap eccentricity

Airgap eccentricity can occur due to manufacturing tolerances, installation procedures (in large motors), other damages or wear and tear.

When the rotor can be considered as rigid and the motor is equipped with rolling bearings, as in the most induction motors, the airgap eccentricity can be distinguished in two types, **static** and **dynamic**, which can exist simultaneously (mixed eccentricity).



L. Frosini

Dynamic eccentricity

Dynamic eccentricity:

The rotor rotates around the stator axis but not around its axis.

The shaft axis does not coincide with the rotor shaft.

Therefore, dynamic eccentricity arouses <u>also a mechanical imbalance</u>, i.e. a centrifugal force rotating at the rotor rotational speed.

It can be caused by incorrect manufacturing (nonconcentric outer rotor diameter), rotor thermal bowing, bearing wear and movement or rotor flexible behavior.



The minimum airgap revolves with the rotor and is a function of space and time L. Frosini

Static eccentricity

Static eccentricity:

The rotor rotates around its axis, which coincides with the shaft axis, but does not coincide with the stator axis.

The rotor is symmetrical to its axis, so there is no mechanical imbalance.

Static eccentricity can be caused by a misalignment due to constructive tolerances, bearings wear, stator core ovality or incorrect positioning of the rotor or stator.



L. Frosini

49

The Maxwell stress tensor

In order to understand what happen in case of eccentricity, it is necessary to calculate the Maxwell stress tensor. The force per unit of surface which tends to close the gap between two blocks of ferromagnetic materials is defined by the **radial component of the Maxwell stress tensor** σ_n and can be expressed in terms of **flux density** *B*, whose lines are perpendicular to the airgap surfaces:

$$\sigma_n = \frac{F_n}{S} = \frac{B^2}{2\mu_0} \left[\frac{\frac{V^2 \cdot s^2}{m^4}}{V \cdot s} = \frac{V \cdot s \cdot A \cdot m}{m^4} = \frac{N \cdot m^2}{m^4} = \frac{N}{m^2} \right]$$

In case of a <u>perfectly concentric rotor and stator</u>, these forces act perpendicularly and symmetrically on the rotor and stator surfaces, so that <u>their resultant is null</u> on the overall circumference.



The Maxwell stress tensor

In induction machines, the magnetic flux Φ at the airgap is determined by the interaction between the magnetomotive forces produced by the stator and rotor windings and it is proportional to the overall m.m.f. M.

In a simplified explanation of the problem, we can consider these magnitudes linked by the simple relationship:

$$\Phi = \frac{M}{\Re}$$

where \Re is the **reluctance** of the magnetic circuit in which the flux Φ flows.

Since the reluctance of the airgap is much higher than that of the iron core, the latter is neglected in the approximated calculation of the m.m.f. required to produce a certain flux Φ .



The Maxwell stress tensor







B =flux density at the airgap [T]

 μ_0 = magnetic permeability of the air [H/m]

 δ = airgap length [m]

S = any perpendicular surface crossed by the flux $[m^2]$

L. Frosini

The Maxwell stress tensor

The main harmonic component of the m.m.f. *M* has a sinusoidal spatial distribution at the airgap, with a period depending on the number of pole pairs p_{a} , and an amplitude which is sinusoidally variable over the time according to the supply frequency *f*. $\beta = \frac{z}{R}$

 $M_1(\beta,t) = \overline{M}_1 \cos(\omega t - p_p \beta)$

As a consequence, even the amplitude of the main harmonic component of the flux density *B* is sinusoidally variable over the time according to the supply frequency *f*.

 $\omega = 2\pi f$

$$B(\beta,t) = \frac{\mu_0 \overline{M}_1}{2\delta} \cos(\omega t - p_p \beta) = \overline{B} \cos(\omega t - p_p \beta)$$
$$\overline{B}$$

L. Frosini

53

The Maxwell stress tensor

The radial component of the Maxwell stress tensor is proportional to the square of the **flux density B**:

$$B^{2}(\beta,t) = \overline{B}^{2} \cos^{2}(\omega t - p_{p}\beta)$$

Knowing that:

$$\cos^2(\alpha) = \frac{1}{2}(\cos(2\alpha) + 1)$$

We obtain:

$$B^{2}(\beta,t) = \frac{1}{2}\overline{B}^{2}\cos(2\omega t - 2p_{p}\beta) + \frac{1}{2}\overline{B}^{2}$$



Therefore, the radial force due to the Maxwell stress tensor has a component which is sinusoidally variable over the time with twice the supply frequency (even in case of uniform airgap).

55

The Maxwell stress tensor

For this reason, the <u>main frequency of the stator case vibration is twice the</u> <u>supply frequency</u> 2f (100 Hz in Europe), even when rotor and stator are perfectly concentric each other.

By integrating the Maxwell stress tensor throughout the airgap, a null resultant is obtained, both in horizontal and vertical direction:

$$F_{x} = \int_{0}^{2\pi} \frac{B^{2}(\beta, t)}{2\mu_{0}} \cos\beta d\beta = 0 \qquad \qquad F_{y} = \int_{0}^{2\pi} \frac{B^{2}(\beta, t)}{2\mu_{0}} \sin\beta d\beta = 0$$

This is valid in case of perfect symmetry between rotor and stator.



Let's see what happens when the rotor and stator are not concentric (skipping some passages of the demonstration).

L. Frosini

Static eccentricity

In case of static eccentricity, the airgap length is given by:

$$\delta(\beta) = \overline{\delta} \cdot (1 + E \cos \beta)$$

But in the expression of the flux density there is the inverse of δ_r therefore the calculation becomes quite complicate. It is possible to demonstrate that the result is:



$$B(\beta,t) = \begin{bmatrix} B_1 \cos(\omega t - p_p \beta) \\ \downarrow \end{bmatrix} = \begin{bmatrix} B_2 \cos(\omega t - (p_p - 1)\beta) \\ \downarrow \end{bmatrix} = \begin{bmatrix} B_2 \cos(\omega t - (p_p - 1)\beta) \\ \downarrow \end{bmatrix} = \begin{bmatrix} B_2 \cos(\omega t - (p_p + 1)\beta) \\ \downarrow \end{bmatrix}$$

a component with p_p pole pairs, a component with as in case of concentric rotor $(p_p - 1)$ pole pairs a component with $(p_p - 1)$ pole pairs

57

L. Frosini

L. Frosini

Effect of static eccentricity on vibrations

In presence of static eccentricity, the flux density is given by the interaction of three harmonics with different number of pole pairs.

In case of static eccentricity, by integrating the Maxwell stress tensor throughout the airgap, a **non-null resultant in the direction of the minimum airgap** is obtained: the <u>steady Unbalanced Magnetic Pull</u> (UMP).

Besides, it can be proven that static eccentricity produces an additional component of the radial force (with respect to the concentric rotor condition) which sinusoidally varies over the time with twice the supply frequency.

Therefore, a vibration increase at 2f(100 Hz), if the supply frequency is 50 Hz) can be expected in presence of static eccentricity.

Effect of static eccentricity on vibrations

Example of approximate distribution of the flux density *B* :



Corresponding distribution of the radial force (proportional to the square of *B*):



UMP = Unbalanced Magnetic Pull

Dynamic eccentricity

In case of dynamic eccentricity, the distribution of the airgap rotate at the rotational speed of the rotor Ω , therefore the length of the airgap can be expressed as:

 $\delta(\beta, t) = \overline{\delta} \cdot (1 + E \cos(\beta - \Omega t))$



Dynamic eccentricity produces a magnetic rotating force (rotating UMP) at the rotational rotor speed Ω (frequency f_r), which is added to the centrifugal force due to the mechanical unbalance (at the same frequency).

L. Frosini

MCSA to detect rotor eccentricity

Regarding the MCSA, for the induction motors it has been proven that the amplitude of the current harmonics at frequencies: $f_s \pm f_r$

- is strongly dependent on the degree of both static and dynamic eccentricity;
- > the effect of the dynamic eccentricity increases from the full load operation to the no-load condition.

D.G. Dorrell, W.T. Thomson, "Analysis of airgap flux, current, and vibration signals as a function of the combination of static and dynamic airgap eccentricity in 3-phase induction motors", *IEEE Trans. Ind. Appl.*, vol. 33, no. 1, 1997, 24-34.

<u>Further current harmonics at frequencies which depends also on the number of rotor slots</u> have been proposed to detect rotor eccentricity and proven to be function of the combination of static and dynamic eccentricity.

J.R. Cameron, W.T. Thomson, A.B. Dow, "Vibration and current monitoring for detecting airgap eccentricity in large induction motors", *IEE Proceedings B - Electric Power Applications*, vol. 133, no. 3, May 1986. W. T. Thomson, R. J. Gilmore, "Motor current signature analysis to detect faults in induction motor drives – fundamentals, data interpretation, and industrial case histories", in *Proc. Thirty-Second Turbomachinery Symposium*, Houston, Texas, Sept. 2003.

L. Frosini

Effect of eccentricity on vibrations

By using the expression of the airgap length in presence of dynamic eccentricity, it is possible to calculate the flux density *B*, similarly to the case of static eccentricity, and hence the Maxwell stress tensor, which is proportional to the square of *B*.

In this way, it can be found that **dynamic eccentricity** also produces **vibrations** at the following frequencies (sidebands around the fundamental):

$$2f_s - f_r$$
 $2f_s + f_r$

By summarizing, for the induction motors it has been proven that the amplitude of the **vibration harmonics** at frequencies: $2f_s$, f_r , $2f_s \pm f_r$

- rapidly increases with both <u>static</u> and <u>dynamic</u> eccentricity, especially at no-load;
- > <u>static</u> eccentricity has only a slight influence on the component at f_r , which, on the other hand, is caused by both the rotating UMP and the mechanical imbalance (both arising from dynamic eccentricity).

L. Frosini

61

Short circuits in stator winding

supplied at low voltage (LV)



Short circuits in stator winding supplied at LV

Short circuits in stator winding can occur:

- 1) between turns of the same phase (turn-to-turn);
- 2) between turns of different phases (phase-to-phase);
- 3) between turns and stator core (phase-to-ground).



Phase-to-phase voltage
 Phase-to-ground voltage
 Turn-to-turn voltage





L. Frosini

Short circuits in stator winding supplied at LV

3.b) Short circuit <u>between</u> <u>turns and stator core</u> in the middle of the slot :



Short circuit on the connections:





Short circuit of the overall

winding:

L. Frosini

Short circuits in stator winding supplied at LV



L. Frosini

65

Short circuits in stator winding supplied at LV

Generally, a stator winding insulation failure begins with a short circuit between turns that involves few turns within the same coil.

With a **turn-to-turn** short circuit, the motor can continue to run, but for how long?

This short circuit generates a <u>high circulation current in the short circuited</u> <u>turns</u>, which causes <u>localized heating</u> and favours a <u>rapid diffusion of the fault</u> to a greater section of the winding.

If not detected, the fault between the turns can propagate and cause phase-to-phase or phase-to-ground failures.

With phase-to-phase or phase-to-ground short circuit, the motor cannot operate and the protective devices disconnect it from its power supply.

67

Diagnostics of short circuits at LV

In low-voltage machines, the time between a **turn-to-turn** short circuit and a **phase-to-phase** or **phase-to-ground** short circuit can take few minutes or few hours, depending on the severity of the fault and on the motor load. So this is a **quickly progressive fault**!

To avoid **phase-to-phase** or **phase-to-ground** short circuits in low-voltage machines, the only solution is to detect the **turn-to-turn** short-circuits by means of an online diagnostic technique.

For LV machines, many manufacturers and operators argue that there is no diagnostic tool that is worth being used to detect **turn-to-turn** short circuits: their idea is that, if a motor starts to fail, it will continue to work until it will breakdown and therefore it will be substituted.

But this principle could be valid only if the failure of the motor will not damage the rest of the system and if there is a spare part of the same motor immediately ready to start to work.

L. Frosini

Diagnostics of short circuits at LV

It is important to observe that, <u>among the on-line diagnostic techniques</u> which can be employed <u>to early detect a potential short circuit</u> in a winding of an electrical machine, <u>there is a clear distinction between</u>:

- the MCSA, to detect inter-turns short circuits in Low Voltage (LV) induction motors (rated voltage < 700 V);
- ✓ the partial discharge monitoring, to diagnose the ground insulation degradation in High Voltage (HV) electrical machines (≥ 700 V).

Note that, under sinusoidal power supply, the insulation systems of LV electrical machines (< 700 V) are not subject to partial discharges.

Nevertheless, partial discharges can happen when LV motors are supplied by inverter.

L. Frosini

Diagnostics of short circuits at LV

In fact, in some cases, an unexpected failure of a low power LV motor can be very expensive or can cause serious safety hazards.

Therefore, even for LV machines, it may be useful to develop a diagnostic tool that allows to early detect a short circuit, in order to plan in advance the replacement of the machine and to avoid more heavy failures.

The literature on this subject has identified as <u>possible indicators of stator</u> <u>short circuits for LV machines</u>:

- the stator current (MCSA), which can be measured by means of a noninvasive instrument as a current probe;
- the stray electromagnetic flux around the motor, which can be collected by means of an external flux sensor.

L. Frosini

69

Flux and current sensors



There are commercial flux sensors which can be

used together with (or instead of) current probes:



Axial flux measurement set up used in this thesis.

V. Kokko, "Condition monitoring of squirrel-cage motors by axial magnetic flux measurements", Academic Dissertation, University of Oulu, 2003.

Both types of sensors must allow the frequency analysis of the acquired signals. Further custom flux sensors can be realized in laboratory.

Characteristic frequencies proposed for the diagnostics of the stator short circuits by means of current and stray flux analysis

Author	Characteristic frequencies	
Penman et al.	$f_s\left(k \pm n\frac{1-s}{p}\right) = kf_s \pm nf_r$	
Stavrou et al.	$(f_s - f_r)$ $f_s\left(N_r \frac{1 - s}{2p} + 2 + 1\right)$	
Thomson	$f_s\left(n\frac{1-s}{p}\pm k\right) = nf_r \pm kf_s$	
Henao et al.	$f_s\left(\gamma \frac{N_r}{p}(1-s) \pm \nu\right)$	
Cruz and Cardoso	$3f_s$	
Romary et al.	$15f_s$, $17f_s$	
f_s = supply frequency f_r = rotational frequency p = number of pole-pair	k = odd i y $n = integrs \gamma = \text{integ}$	

- ✓ J. Penman, H.G. Sedding, B.A. Lloyd, W.T. Fink, "Detection and location of interturn short circuits in the stator windings of operating motors," IEEE Trans. Energy Convers., vol. 9, no. 4, pp. 652-658, 1994.
- A. Stavrou, H.G. Sedding, J. Penman, "Current monitoring for detecting inter-turn short circuits in induction motors," IEEE Trans. Energy Convers., vol. 16, no. 1, pp. 32-37, Mar 2001
- W.T. Thomson, "On-line MCSA to diagnose shorted turns in low voltage stator windings of 3-phase induction motors prior to failure," in Proc. IEMDC 2001, pp. 891-898.
- H. Henao, C. Demian, G.A. Capolino, "A frequency-domain detection of stator winding faults in induction machines using an external flux sensor," IEEE Trans. Ind. Appl., vol. 39, no. 5, pp. 1272-1279, 2003.
- ✓ S.M.A. Cruz, A.J.M. Cardoso, "Diagnosis of stator interturn short circuits in DTC induction motor drives," IEEE Trans. Ind. Appl., vol. 40, no. 5, pp. 1349-1360, 2004.
- ✓ R. Romary, R. Pusca, J. P. Lecointe, J. F. Brudny, "Electrical machines fault diagnosis by stray flux analysis," in Proc. WEMDCD 2013, pp. 245-254.

integer positive number (k = 1, 3, 5, ...)

- ger positive number $(n = 1, 2, 3, \dots 2p-1)$
- γ = integer positive or null number (γ = 0, 1, 2, 3, ...) v = harmonic index of the stator current

73

L. Frosini

s = slip

 N_r = number of rotor bars

Short circuits detection with current and flux

In this significant paper, the efficiency of the stator winding fault detection based on the stray flux and stator current analysis was tested on a threephase induction motor, 11 kW, 230/400 V, 50 Hz, 4 poles.

A stray flux sensor and a stator current probe have been connected to the same data acquisition board through two voltage amplifiers, to scale the magnitude of the signals, and through two low-pass anti-aliasing filters, to set the frequency bandwidth to a correct range.

The current and the stray flux have been analyzed in both the time and frequency domain, initially with the motor at standstill.

The power supply has been fed either by the grid or by a VSI (voltage source inverter), in order to test the robustness of the proposed method also in presence of harmonics coming from the voltage source.

L. Frosini

An example of short circuits detection with current and flux



H. Henao, C. Demian, G.A. Capolino, "A frequency-domain detection of stator winding faults in induction machines using an external flux sensor", IEEE Trans. Ind. Appl., 39(5), pp. 1272-1279, 2003.

L. Frosini

Short circuits detection with current and flux

The data acquisition board is set for a 250 kHz sampling rate, with low-pass anti-aliasing filters, having a cutoff frequency of 2 kHz.

The current probe is a Rogowski coil with an external analog amplifier.

The stray flux sensor is a 1000 turns air coil, placed near the machine body and connected to a voltage analog amplifier with variable gain.



The motor has been rewound on purpose, with a phase circuit having the first turns (from 1 to 6) being accessible from the outside.

This arrangement allows to perform an inter-turns short circuit, at a reasonable level (from 1% to 6% of the phase impedance).

The short circuit current in the winding is limited by an adjustable resistance, to keep it not higher than the rated value, for not damaging the motor.

Analysis in the time domain of current and flux



The stray flux shows greater distortion when the fault is present.

In this case, the analysis in the time domain is sufficient to detect the fault.



0.29

Analysis in the time domain of current and flux



By supplying the motor with a VSI, at the same fundamental frequency, the distortion of the flux increases more than the current.

L. Frosini

Analysis in the frequency domain





connected directly to the grid

At the top: healthy. At the bottom: faulty.

The current seems not sensible to the fault.

The two stray flux spectra are very different: the fault is identified by the increase of the harmonics at 150 Hz (3f) and 450 Hz (9f).

L. Frosini

77

Analysis in the frequency domain



At the top: healthy. At the bottom: faulty.

Again, the current seems not sensible to the fault,

Motor at standstill connected to the VSI

whereas the stray flux spectra are very different: the fault is still identified by the increase of the harmonics at 150 Hz (3f) and 450 Hz (9f).



250Hz

Flux

631Hz

731Hz

1650Hz

f[Hz]



These are the normalized spectra during the operation at **rated load**, with the **healthy motor**: the number of excited harmonics increases.

81

L. Frosini

Short circuits detection with current and flux

This method was initially tested with the motor at standstill, and then in operation, until the rated load.

During the operation at rated load, the number of excited harmonics increases (even in the healthy motor) and the fault detection becomes more complex.

In general, this technique seems quite easy to implement, with low cost tools. It looks promising for industrial applications, as it is non-invasive and does not require any particular precaution for its installation.

Nevertheless, the effectiveness of this diagnostic technique in industrial applications to detect short circuits in low voltage motors has still to be proven. Moreover, it is necessary to evaluate the economic convenience of the application of this technique for each particular case.

L. Frosini

Analysis in the frequency domain



These are the normalized spectra during the operation at **rated load**, with 6% of short-circuited turns.

It has been observed that, when short circuit is present, the rotor speed decreases, as the electromagnetic torque produced by the motor decreases.

L. Frosini

Bearing faults



Bearing faults

Bearing faults can happen due to the following main causes:

- Normal fatigue (wear and tear);
- □ Contamination (airborne dust, dirt or any abrasive substance);
- □ Improper lubricant or poor lubrication;
- □ Corrosion (corrosive fluids or corrosive atmosphere)
- □ Shaft voltage (bearing currents)
- Excessive load
- □ Misalignment
- Overheating





Most of these causes (but not all) arouse slowly progressive bearing faults!

L. Frosini

Periodical vs. predictive maintenance

For these reasons, over recent years, many studies have been focused on the implementation of a **predictive condition monitoring** scheme able to detect bearing faults in their incipient stage by means of online continuous measurement and analysis of variables **easy to collect, noninvasive** and **low cost**:

- \succ vibration, \longrightarrow well consolidated methodology for these faults
- ➤ current,
- ➤ stray flux.

This detection scheme needs to categorize bearing faults into two main groups:

- single-point defects (cyclic);
- generalized roughness (non-cyclic).

L. Frosini

Periodical vs. predictive maintenance

For this reason, the **common practice** to detect bearing faults in low voltage motors is a combination of:

 a periodical condition monitoring of the motors, in which expert technicians collect and elaborate vibration measurements by means of sensors, normally not permanently installed on the machines;



a periodical preventive substitution and/or lubrication of the bearings after a given number of hours indicated by the manufacturer.

This periodical maintenance is generally effective, but:

- it is **expensive** and normally needs the employment of personnel and instruments **external** to the firm;
- it can require early unnecessary substitution of bearings;
- it **can fail** in case of <u>quickly progressive</u> faults, as those due to shaft currents caused by electronic converters.

L. Frosini

Effects of single-point defects on vibrations

A <u>single-point defect</u> produces an impact between the ball and the raceway and generates detectable **vibrations** at predictable frequencies f_{ν} which depend on:



- surface of the bearing which contains the fault (outer race, inner race, ball, cage);
- geometrical dimensions of the bearing;
- rotational speed of the rotor f_r .

The theoretical frequency to monitor in the vibration spectrum to detect a fault in the <u>outer race</u> is: N =number of rolling elements (ball or roll)

$$f_o = \frac{N}{2} f_r \left(1 - \frac{d}{D} \cos \alpha \right)$$

d = diameter of the rolling element D = bearing pitch diameter

 α = ball contact angle, which is equals to 0° for deep-groove ball bearings.

Effects of single-point defects on vibrations

To detect a fault in the inner race:

For a defect in the rolling elements:

 $f_b = \frac{D}{2d} f_r \left(1 - \left(\frac{d}{D}\right)^2 \cos^2 \alpha \right)$ $f_c = \frac{1}{2} f_r \left(1 + \frac{d}{D} \cos \alpha \right)$

 $f_i = \frac{N}{2} f_r \left(1 + \frac{d}{D} \cos \alpha \right)$

For a defect in the cage:

For simplicity, the outer and the inner race characteristic frequencies can be approximated for most bearings by:

 $f_o = 0.4 \cdot N \cdot f_r$ $f_i = 0.6 \cdot N \cdot f_r$



89

L. Frosini

MCSA to detect bearing faults

The relationship between the bearing vibration and the stator current of an induction motor can be determined by remembering that any airgap eccentricity produces an asymmetry in the flux density at the airgap.

In turn, this asymmetry affects the inductances of the machine which determine the harmonics of the stator current.

Since rolling bearings support the rotor, any bearing defect produces a radial displacement between rotor and stator.

Therefore, the radial motion produced by a single-point defect arouses stator current components at predictable frequencies f_p :

 $f_p = |f_s \pm kf_y|$ $f_s =$ supply frequency

where f_{v} is one of the characteristic vibration frequencies to detect a singlepoint defect and $k = 1, 2, 3, \dots$

I. Frosini

Vibration analysis for single-point defects

Example of vibration analysis in the frequency domain (inner race fault):

5: Frequency spectrum of envelope signal between 0 and 200 Hz, below: undamaged bearing; above: damaged bearing n_{IR} Inner ring speed [min⁻¹] Frequency of inner ring signal (cycling frequency) [Hz]



L. Frosini

MCSA to detect bearing faults

Since 1995, many studies have been focused on the possibility to employ the motor current signature analysis (MCSA) as an alternative diagnostic index for bearing faults, with respect to the vibration measurements.

After 2006, even the external stray flux has been considered with the same purpose.



- ✓ R. R. Schoen, T. G. Habetler, F. Kamran, and R. G. Bartheld, "Motor bearing damage detection using stator current monitoring," IEEE Trans. Ind. Appl., vol. 31, no. 6, pp. 1274-1279, Nov./Dec. 1995.
- ✓ M. D. Negrea, "Electromagnetic Flux Monitoring for Detecting Faults in Electrical Machines," Ph.D. Thesis, Department of Electrical and Communications Engineering, Helsinki University of Technology, Espoo, Finland, 2006.

Generalized roughness

Generalized roughness is a very common fault in rolling bearings, but it has not been sufficiently considered in the literature.



Since <u>generalized roughness is not a single-point defect</u>, the characteristic fault frequencies are not expected to be excited and their monitoring could be ineffective to detect this fault.

Only few studies have been dedicated to discover a generalized roughness by means of MCSA and very few by means of the stray flux analysis.

- J. R. Stack, T. G. Habetler, and R. G. Harley, "Bearing fault detection via autoregressive stator current modeling," *IEEE Trans. Ind. Appl.*, vol. 40, no. 3, pp. 740-747, May/Jun. 2004.
- ✓ W. Zhou, B. Lu, T.G. Habetler, and R.G. Harley, "Incipient Bearing Fault Detection via Motor Stator Current Noise Cancellation Using Wiener Filter," *IEEE Trans. Ind. Appl.*, vol. 45, pp. 1309-1317, no. 4, Jul./Aug. 2009.
- ✓ A.M. Knight and S.P. Bertani, "Mechanical fault detection in a medium sized induction motor using stator current monitoring," *IEEE Trans. Energy Convers.*, vol. 20, no. 4, pp. 753 760, Dec. 2005.
- F. Immovilli, M. Cocconcelli, A. Bellini, and R. Rubini, "Detection of generalized-roughness bearing fault by spectralkurtosis energy of vibration or current signals," *IEEE Trans. Ind. Electr.*, vol. 56, pp. 4710-4717, no. 11, Nov. 2009.

L. Frosini

The test-bench

The bearing faults have been simulated on a three-phase induction motor, $P_n = 2.2 \text{ kW}$, 2 poles, $n_n = 2800 \text{ rpm}$, supplied by the mains (400 V, 50 Hz) and joined with a magnetic powder brake.



L. Frosini

MCSA to detect generalized roughness

In our laboratory, we have tried to diagnose the presence of **generalized roughness** by means of the analysis of both the **current** and the **stray flux** signals.

Previously, we have examined other bearing faults by means of the analysis of current and stray flux, but considering only the harmonics multiple of the fundamental.

L. Frosini, C. Harlişca, and L. Szabó, "Induction machine bearing faults detection by means of statistical processing of the stray flux measurements," *IEEE Trans. Ind. Electron.*, vol. 62, no. 3, March 2015.





Fig. 5. Absolute value of the integer harmonics difference

Then, we have decided to pay attention also to the characteristic harmonics derived from the equations of the single-point bearing defects.

L. Frosini

The test-bench

The ball bearings are double-crown, with a plastic cage which allows a simple disassembly of the balls. **Generalized roughness** was artificially created on all the balls of a bearing, at **three progressive stages**, by immersing the balls in a solution of concentrated sulfuric acid.

Therefore, four conditions of the bearing are available:









Healthy GC1, GC2

95

Damage step 1 GC3, GC4 Damage step 2 E GC5, GC6

The experimental tests

The motor was tested in **8 different cases (GC1, GC2, ... GC8)**: two cases (at no-load and at 75% of the rated load) for each condition of the bearing.

In the **faulty cases (from GC3 to GC8)**, the drive-end bearing of the motor was substituted with one of the artificially damaged bearings.

In order to obtain a robust diagnosis from a statistical point of view, for each case, a set of 40 acquisitions was collected: each acquisition consists of 2¹⁹ samples, gathered with a sampling frequency of 20 kHz.

In each acquisition, 3 variables have been measured in a synchronous way:

- a) current of one phase;
- b) axial leakage flux, by means of a commercial probe;
- c) radial leakage flux, by means of a custom probe.

L. Frosini

The experimental tests

- Each acquisition has been transformed in the frequency domain, in the range 0÷2000 Hz.
- The mean and the standard deviation of the 40 spectra related to each set of acquisitions have been calculated.
- The mean of the spectra related to each healthy case has been compared with the corresponding faulty cases.

We decided that the warning of possible fault is present when an excited harmonic appears within a range of ± 5 Hz around each characteristic frequency of fault. This "range of sensitivity" permits to overcome possible misunderstandings due to measurement errors or to small changes in the mechanical speed of the rotor, in order to make more robust the fault detection in industrial environment.

97

L. Frosini

The experimental results

In the following tables, the <u>characteristic frequencies of the single-point</u> <u>bearing faults</u> are reported, when the related harmonics reveal a difference in amplitude between the healthy and the faulty cases <u>higher than three times</u> <u>the standard deviation</u> of the healthy case.

Comparison	Variable	Characteristic harmonics [Hz]
CC2.00 CC1	Current	640
	Emerson flux	540 , 640
no-ioad, step i	Custom flux	300 , 540 , 1400, 1500
	Current	930, 1030
GC4 vs. GC2	Emerson flux	30 , 300 , 400, 440, 520, 540 , 640, 930, 1030 , 1425, 1910
75761020, Step 1	Custom flux	300 , 400, 440, 520, 540 , 930, 1030 , 1425, 1525

L. Frosini

The experimental results

Comparison	Variable	Characteristic harmonics [Hz]
	Current	185
BCS VS. BCT	Emerson flux	
no-ioad, step 2	Custom flux	185, 300 , 540 , 1400, 1500
CC6 vs CC2	Current	
75% load stop 2	Emerson flux	30 , 520
7576 load, step 2	Custom flux	540
Comparison	Variable	Characteristic harmonics [Hz]
	Current	70, 285, 300
GC7 vs. GC2	Emerson flux	30 , 70, 90, 170, 185, 285, 300 , 400, 420, 440, 520, 540 , 640, 670, 770, 930, 1030 , 1400, 1420,
no-ioad, step 3	Custom flux	5, 30 , 70,, 170, 185, 285, 300 , 400, 420, 440, 520, 540 , 640, 670, 770, 930, 1030 , 1400, 1425,
	Current	300 , 520
GC8 vs. GC2	Emerson flux	30 , 70, 105,, 170, 190, 285, 300 , 400, 420, 440, 520, 540 , 640, 670, 770, 930, 1030 , 1400, 1425,
7 5 % 10 40, step 3	Custom flux	30 , 185, 285, 300 , 400, 420, 440, 520, 540 , 640, 670, 770, 930, 1030 , 1400, 1425, 1500, 1520, 1910

The experimental results

Observations:

- the stray flux presents a more consistent diagnostic content with respect to the stator current, so its use as diagnostic indicator seems promising;
- the frequencies highlighted in bold are common to almost all the examined cases;
- the <u>characteristic frequencies of the single-point bearing defects seem</u> <u>significant also in case of generalized roughness</u>, provided to neglect the selectivity of the damaged component;
- the analysis of these frequencies has to be completed with the monitoring of the trend of all the harmonic spectrum;
- the detection ability of the custom flux probe seems more effective with respect to the commercial flux sensor.

L. Frosini

The experimental results

Differences between the means of the spectra of the **custom flux** related to the cases GC1 and GC3 (no-load, **step 1**):



L. Frosini

The experimental results





The experimental results

Differences between the means of the spectra of the **custom flux** related to the cases GC1 and GC7 (no-load, **step 3**):



Note that, when the motor is supplied by inverter, the fault detection by means of the stator current and stray flux analysis becomes more complex, since the electromagnetic signals are more "dirty" and disturbed by the harmonics introduced by the inverter (specific algorithms for filtering the signals are needed).

The experimental results

A thermal analysis can help in detecting a bearing fault (the dimension of the "red area" increases with the damage degree):



105

Thank you very much for your kind attention!

